





FRESAS / MILLING CUTTERS

CODE	A	B	C	D	E	PARA-FOR	MAT
F1	90	0,8		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F1A	90	0,8		45	8	CAPRI-CAPRI S.-NEO-XCODE	HSS
F1W	90	0,8		45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F3			1,5	45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F3W			1,5	45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F4	90	0,4		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F5	90	0,9		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F5W	90	0,9		45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F6	106	1		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F7	70	0,8		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F8			4	45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F8W			4	45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F9			5,95	45	6	CHICAGO	HSS
F9W			5,95	45	6	CHICAGO	W
F11			2,5	45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F11W			2,5	45	6	XCODE	W
F11A (FIC-2)			2,5	45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F12A	100	0,6		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F12B	100-90	2,1-2,9		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F13	100	0,8		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F13W	100	0,8		45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F14	100	1,45		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F15 + plantillas		2	5	45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F16	130	0,6		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F17			3	45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F17W			3	45	6	XCODE	W
F19	90	1,2		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F19W	90	1,2		45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F21	85	0,72		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F22			2,4	45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F23	90	0,8	3,3	45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS

CODE	A	B	C	D	E	PARA-FOR	MAT
F23W	90	0,8	3,3	45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F24W	95	1		45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F25W	95	1,1		45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F27	90	0,7		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F27W	90	0,7		45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F28W	60	1,4		45	6	XCODE	W
F29W	100	0,6		45	6	XCODE	W
F30W	100	0,5		45	6	XCODE	W
F31W	90	0,6		45	6	XCODE	W
F32	90	0,6	3	45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F32W	90	0,6	3	45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F33			2	45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F33W			2	45	6	XCODE	W
F34	90	1,4		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F-35W	90	3	3	45	6	CAPRI-CAPRI S.-NEO-XCODE	W
F-40	90	0,2		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F-40W	90	0,2		45	6	XCODE	W
F43	90	0,7		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F-49W	83,52	0,8		45	6	XCODE	W
FB	90-90	2,7-3,3		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
FC	80-80			45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
FBW	90-90	2,7-3,3		45	6	CAPRI-CAPRI S.-NEO-XCODE	W
FCW	80-80			45	6	CAPRI-CAPRI S.-NEO-XCODE	W
FS-31	60-60	0,64-0,95		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS

CODE	F	G	C	D	E	PARA-FOR	MAT
F18	10	1		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F20	16	1,25		45	6	CAPRI-CAPRI S.-NEO-XCODE	HSS
F36	12	2		45	6	XCODE	HSS
F37	12	1,3		45	6	XCODE	HSS



SIMBOLOGÍA / SYMBOLS

W

Fresa de metal duro
Metal gogorreko fresa
Hard metal cutters
Fraise en métal dur
Hartmetallfräse

HSS

Acero extra rápido
Altzairu estra azkarra
High-speed steel
Acier extra rapide
Extraschneller Stahl



Diámetro
Diametroa
Diameter
Diametre
Durchmesser



Altura de corte
Ebaketa altuera
Cutting height
Hauteur de coupe
Schnitthöhe



Diámetro de corte
Ebaketa diametroa
Cutting diameter
Diàmètre de coupe
Schneidmesser



Ángulo de corte
Ebaketa-angelua
Cutting angle
Angle de coupe
Schnittwinkel



Base
Oinarri
Base
Base
Basis































Distancia corte
Ebaketaren distantzia
Cutting distance
Distance coupe
Schnittabstand



Largo
Luzeera
Length
Longueur
Länge















FRESAS / MILLING CUTTERS

																				
F-1	F-1A	F-1W	F-3	F-3W	F-4	F-5	F-5W	F-6	F-7	F-8	F-8W	F-9	F-9W	F-11	F-11A	F-11W	F-12A	F-12B	F-13	F-13W
																				
F-14	F-15	F-16	F-17	F-17W	F-18	F-19	F-19W	F-20	F-21	F-22	F-23	F-23W	F-24W	F-25W	F-26	F-27	F-27W	F-28W	F-29W	F-30W
																				
F-31W	F-32	F-32W	F-33	F-33W	F-34	F-35W	F-36	F-37	F-40	F-40W	F-43	F-49W	F-B	F-BW	F-C	F-CW	F-S31			



PALPADORES / TRACERS

																			
P-1	P-3	P-4	P-5	P-6	P-7	P-8	P-11	P-12A	P-12B	P-12X	P-13	P-14	P-15	P-16	P-18	P-19	P-21	P-22	P-23
																			
P-26	P-32	P-33	P-34	P-36	P-40	P-43	P-B	P-C	PS-31										